
GUNSITE CIRCUIT PLAN



Planned Work:

 New covered conductor has already been installed on all overhead portions while repairs were made following a 2020 fire

Expected Improvements:

• **18% reduction** in customer outage time, assuming the same weather conditions in 2020